


CC021 Installation Instruction








Board name and serial number:


Knock in the embedded part I in the non-penetrating small hole, and then screw on the eccentric screw Α























door adjustment

The door gap is too large






As shown in the figure, the screw that the screwdriver points to,

It is to adjust the left and right movement of the door

panel, and the clockwise rotation is to adjust the door panel to move to the middle.




As shown in the picture, loosen the screw pointed by the screwdriver, push the door panel in or pull it out, and then

The gap between the door panel and

the side panel is too large

tighten it to solve the above problem.





As shown in the picture, loosen the screw pointed

by the screwdriver, push the lower door panel and hinge upward, and then tighten

the screw. Push the higher door panel and hinges down and tighten the screws.